

STEP 10

HEAT MIXTURE OF RHO-ISO-ALPHA-ACIDS TO FLUID STATE

STEP 12

STIR HEATED MIXTURE OF RHO-ISO-ALPHA-ACIDS

STEP 14

ADD AQUEOUS POTASSIUM HYDROXIDE SOLUTION TO MIXTURE OF
HEATED/STIRRED RHO-ISO-ALPHA-ACIDS

STEP 16

COOL AQUEOUS SOLUTION OF POTASSIUM SALTS OF RHO-ISO-ALPHA-ACIDS
TO ROOM TEMPERATURE

FIG. 1




FIG. 2